


Packing instruction

You should pack your machine well if you need to transport it. This document explains how the new type of case with padding is intended to use.



- The thinner pads (A) are put on the left and right side.
- The two bigger thick pads (B) are put upright at the back of the machine.
- The two smaller thick pads (C) are put flat at the front of the machine.